

Procedure: C-A-OCF-002-EBC

Revision: 03

Revision Date: 03/15/04

COLLIDER-ACCELERATOR DEPARTMENT

Title: Operational Control Form For Beam-line Construction and Disassembly

Prepared by: M. Van Essendelft

Group: ESH&Q

Approvals

		Signature on File	Date:				
ESH&Q Division Head							
		Signature on File	Date:				
Collider-Accelerator Department Chairman							
(Indicate additional signatures)							
-	N x	FS Representative:	Date:				
	X	Radiological Control Coordinator:	Date:				
	X	Chief ME:	Date:				
	X	Chief EE:	Date:				
X		Environmental/P2 Coordinator: Signature on File	Date:				
	X	QA Manager:	Date:				
	X	Other:	Date:				

BNL ENVIRONMENTAL MANAGEMENT SYSTEM OPERATIONAL CONTROLS FORM

Operational Control
For Significant Environmental Aspects

Completed By: M. Van Essendelft

Date: ____March 15, 2004_

1. Operation(s): Beam-line Construction/Disassembly

2. Activity(ies):

Hazardous, industrial and radioactive waste generation

3. Operational Controls (technological, operational, procedural operating criteria):

- C-A OPM 8.20, Handling and Disposing of Hazardous Waste
- C-A OPM 8.20.2, Radioactive Waste Disposal
- C-A OPM 8.22, Handling and Disposal of Non-Hazardous and Recyclable Solid Waste
- C-A OPM 2.28, Enhanced Work Planning (C-A version of ES&H Std. 1.3.6)
- C-A OPM 1.19, Procedure for Determining Applicability and Obtaining a Permit to Perform Work that Impacts the Exterior of the RHIC
- Secondary containment of stored waste
- Tier I program and C-A self-assessment program
- Applicable SBMS subject areas

4. Maintenance Plan(s):

None

5. Actions to be Taken if Controls Fail:

- Call spill response hotline 2222 or 911
- See C-A OPM 3.0, Local Emergency Plan For the C-A Department

2

6. Records

- Tier I Inspection records / Tracking Database
- Operational Control Form
- Process Assessment Form / Corrective Action, P2 Measures, and Assessment, Prevention & Control Initiatives Tracking Database
- C-A Family ATS documentation on completion of Environmental Management Program, Section 10 Tasks
- Satellite Area inspections records

7. Responsibilities: [(a) to ensure controls are in place; (b) to ensure controls keep working; (c) to						
take action when controls fail; (d) to create and keep records relative to operational controls						
Name		Responsibility				
Facilities and Experimental Supp and C-A Environmental Coordina	` '	Ensure proper collection and disposal of hazardous, radioactive or mixed waste				
Tier I Inspection Committee		Tier I documentation				
C-A Waste Management Represe	entative	Satellite Area inspection				
8. Training:	Training		Date			
Facilities and Experimental Support (FES) Group and C-A Environmental Coordinator	Hazardous Waste Generator Radioactive Waste Generator		NA NA			
Building Staff See also: EMS package for this			NA			